## **LD PIPE RACK Mounting Instructions**



## Step 1

Mount bracket "A" on rail with placard. (See figure 1)

Drill through hole for mounting bolts.

## Figure 1 (Steering End of MEWP) derstand and obey the operator's ma or serious injury. Tip-over Hazards Do not exceed rated load capacity. Do not raise platform unless machine is on surface. Avoid drop-offs, holes and unstable nachine operation. This includes: Avoid hazardous situations. slippery surfaces. Always perform a pre-operation inspection. Always perform function tests prior to use. 5 Only use the machine as it was intended. Do not operate unless: You read, understand and obey safety and operator's - employer's safety rules - applicable governmental regulations

## Step 2

Mount bracket "B" on opposite end (see figure 2).

Use supplied bolts to attach.

